




LW53

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com






JBA
consulting



JBA Groundwater Emergence Map


 Site Boundary


Groundwater Level

-  Less than 0.025m below the ground surface
-  Between 0.025m and 0.5m below the surface
-  Between 0.5m and 5m below the ground surface
-  At least 5m below the ground surface
-  Negligible risk of groundwater emergence due to underlying geological deposits

Contains OS data © Crown copyright and database right (2025). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.

www.jbaconsulting.com






TK17

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com

JBA
consulting



JBA Groundwater Emergence Map

Site Boundary

Groundwater Level

- Less than 0.025m below the ground surface
- Between 0.025m and 0.5m below the surface
- Between 0.5m and 5m below the ground surface
- At least 5m below the ground surface
- Negligible risk of groundwater emergence due to underlying geological deposits

Contains OS data © Crown copyright and database right (2025). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.



TK27

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com






JBA
consulting



JBA Groundwater Emergence Map


 Site Boundary


Groundwater Level

-  Less than 0.025m below the ground surface
-  Between 0.025m and 0.5m below the surface
-  Between 0.5m and 5m below the ground surface
-  At least 5m below the ground surface
-  Negligible risk of groundwater emergence due to underlying geological deposits

Contains OS data © Crown copyright and database right (2025). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.

www.jbaconsulting.com





1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com



JBA Groundwater Emergence Map

- Site Boundary
- Groundwater Level**
 - Less than 0.025m below the ground surface
 - Between 0.025m and 0.5m below the surface
 - Between 0.5m and 5m below the ground surface
 - At least 5m below the ground surface
 - Negligible risk of groundwater emergence due to underlying geological deposits


Contains OS data © Crown copyright and database right (2025). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.



TC71

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com






JBA
consulting



JBA Groundwater Emergence Map



 Site Boundary


Groundwater Level

-  Less than 0.025m below the ground surface
-  Between 0.025m and 0.5m below the surface
-  Between 0.5m and 5m below the ground surface
-  At least 5m below the ground surface
-  Negligible risk of groundwater emergence due to underlying geological deposits

Contains OS data © Crown copyright and database right (2025). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.

www.jbaconsulting.com






Madeley High School Extension

1 Broughton Park
Old Lane North
Broughton
Skipton
North Yorkshire
BD23 3FD
+44 (0)1756 799 919
info@jbaconsulting.com






JBA
consulting



JBA Groundwater Emergence Map

 Site Boundary

Groundwater Level

-  Less than 0.025m below the ground surface
-  Between 0.025m and 0.5m below the surface
-  Between 0.5m and 5m below the ground surface
-  At least 5m below the ground surface
-  Negligible risk of groundwater emergence due to underlying geological deposits

Contains OS data © Crown copyright and database right (2025). This document is the property of Jeremy Benn Associates Ltd. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the permission of Jeremy Benn Associates Ltd.